

## DD243:2004 - Changes since DD243:2002

This summary is provided as a guide only - for full details, consult DD243:2004...

Clause	Change	Notes
4.2	Emphasises that ALL systems should incorporate sequential confirmation technology.	
4.3	Confirmation including one or more transmission path faults must now occur within maximum of 96 hours (still within a single set period). Additional guidance notes for installer.	
5.4.2	Original clause split into two: New 5.4.2: Applicable specifically to use of movement detectors with overlapping areas of coverage. "Located some distance apart" has been adjusted to "normally located with housings at least 2.5 metres apart" New 5.4.3: Applicable specifically to use of movement detectors with non-overlapping areas of coverage. Permits two detectors to be mounted in the same housings, provided that this is declared at installation, and included on application for URN.	So that police can force a system change if these detectors cause FAs.
5.4.3	Original clause now 5.4.4	
5.4.4	Original clause now 5.4.5	
6.3	Reference to "other means when using EN50131" has been removed.	
6.4.1	General clause about unsetting amplified. Now specifically mentions the use of external ACE for unsetting. Requires that application of force to external ACE cannot initiate change of status of IAS	
6.4.2	Adjusted so that permits additional methods of ensuring that IAS is unset before entry is possible.	6.4.2 / 3/ 4 are "preferred" methods. 6.4.5 carries warnings.
6.4.3	Adjusted so that permits additional methods of ensuring that confirmation is disabled before entry is possible.	
6.4.4	Option remains, with additional notes for guidance of installer.	
6.4.5	Method unchanged. Includes concession to use of PIN code for unsetting after expiry of entry time, and mentions use of external ACE (with PACE only). Includes scenario where unconfirmed alarm takes place BEFORE start of entry time. "Zone Omit Rearm" <b>must</b> now be advised to keyholder.	
6.4.6	Additional notes for guidance of installer.	
7.1	If sounds are inconclusive, ARC must NOT consider it confirmed. Rather, wait for additional information.	
7.2	If images are inconclusive, ARC must NOT consider it confirmed. Rather, wait for additional information.	
A.3.1	Clarifies that, for EN50131 event logging purposes, each "confirmation period" is treated as a separate "set" period.	
A.3.2	Additional note re advice to keyholder of zones isolated by ARC.	
F	New annex summarising all information required to be included in system documentation	